

Fabrics and leathers

List of fabrics and technical characteristics

CAT	FABRIC/LEATHER	COMPOSITION	H	WEIGHT GR/SQ.MT	FADING	MARTINDALE	PILLING	WASHING INSTRUCTIONS	SCHRINK
A	CANVAS (sanfor)	100% cotton	140	425	5/6			<td>2-3%</td>	2-3%
A	POLARIS	87% polyvinyl chloride 13% polyamide	140	700				<td>2%</td>	2%
A	TELE (A51)	100% cotton	160	209				<td></td>	
A	TELE (A61)	100% linen	140						

Washing Instruction

Symbols Explanations

Symbols Description and definitions



Washing



Bleaching



Ironing



Dry cleaning



Drying



Treatment not allowed

The cross placed on any of the above treatments states that such treatment is not allowed.



Moderate treatment

The bar underneath the washing and the dry cleaning means that the treatment has to be more moderate compared to the treatment without the bar.



Very moderate treatment

The interrupted bar underneath the washing means that the treatment has to be very moderate at 40°

Washing

	Temp. max	Action	Rinsing	Drying	Various
	95°	regular	regular	regular	
	95°	moderate	With cooler water	moderate	
	70°	regular	regular	regular	
	60°	regular	regular	regular	
	60°	moderate	With cooler water	moderate	
	50°	moderate	With cooler water	moderate	
	40°	regular	regular	regular	

Washing Instruction

	Temp. max	Action	Rinsing	Drying	Various
	40°	moderate	With cooler water	moderate	
	40°	Very moderate	regular	regular	
	32°	Very moderate	regular	moderate	
	40°				- hand wash only - no machine washing - handle with care
					- do not water wash - if damp, handle with care

Bleaching – The triangle indicates chlorine bleaching treatment







Allowed
- only diluted with cold water

Not allowed


Ironing

- ironing at hot temperature
- ironing at medium temperature
- ironing at low temperature
- do not iron
- steam ironing not allowed

Dry cleaning

-  - all solvents allowed
-  - Dry cleaning with perchlorethylene solvents
-  - Dry cleaning with solvents as above
- Severe limitations with water addition to the process
-  - Dry cleaning with hydrocarbons
-  - Dry cleaning with hydrocarbons as above
- Severe limitations with water addition to the process
-  - Dry cleaning not allowed
- Solvents not allowed

Drying

-  - Do not spin-dry
-  - Tumble dry
-  - Tumble dry low
-  - Do not put in the dryer
-  - Line dry